



Materials Science



Stress + Strain

Definitions

FOS: ultimate strength
allowable stress



$$\sigma = \frac{F}{A}$$

force
cross section area

$$\epsilon = \frac{l - l_0}{l_0}$$

l : final length
 l_0 : initial

Elastic Region: slope in elastic region measures stiffness E (young mod)

- High E means stiffer material
- Elastic deformation is reversible material returns to original shape
- Proportional limit - max point where σ & ϵ are directly proportional.

Yield Point: stress @ which permanent (plastic) deformation occurs.

- Some materials have distinct yield point others you can find using the offset method (α) (e.g. 0.2% strain) to find yield strength.


Plastic Region: irreversible deformation when material stressed beyond yield

Ultimate Tensile Strength: max stress before necking will occur.

Necking: localized reduction in cross sectional area before fracture

Fracture: the point at breakage. Brittle fracture little to no plastic deform.
Ductile has sig plastic deform before fail.


Ductile vs Brittle stress strain curves



Toughness = the ability to absorb energy up to fracture
 = the total area under the strain-stress curve up to fracture

Brittle Material: Elastic region linear until sudden fracture with no plastic low strain to failure (remember what Σ formula is)

Aluminum vs Steel SS Curve



$E_{Al} \approx 70 \text{ GPa}$ - Aluminum
 $E_{St} \approx 210 \text{ GPa}$ - Steel

- Most mild/low carbon steels exhibit yield point phenomenon YPP.
- YPP occurs bc carbon atoms at interstitial sites of steel microstructure that require high stress to slip (γ_1) but stress falls after dislocation lines move past γ_1
- Higher strain hardening as deforms plastic
- Higher elongation before fracture

Ductile Hooke's law

Elastic region: linear slope up to yield point

Plastic region: Stress remains const as strain \uparrow then stress \uparrow as material strengthens due to defor then localized thinning precedes fracture


Aluminum:

- Lightweight $\frac{1}{3}$ density of steel
- Lower stiffness and strength
- Lower YM simplifies forming
- Density: 7.85 g/cm^3
- Losses strength at temps $> 200^\circ \text{C}$
- Naturally forms protective oxide layer



Steel:

- Higher strain hardening as deforms plastic
- Higher elongation before fracture

MODS



Beam Bending : when a mechanical member is subjected to pure bending due to an applied load



Flexure Formula :

$$\sigma = -\frac{My}{I}$$

σ = bending stress

M = moment due to load

I = second moment of inertia

Moment of Inertia : denoted as I quantifies resistance of cross sectional area to bending or rotation.



for rectangular geometry:

$$I = \frac{bh^3}{12}$$




since h is cubed
it has larger effect on I

Parallel Axis Theorem: allows you to calculate moment of inertia of cross sectional area about axis parallel to centroidal one.

$$I_{\text{parallel}} = I_{\text{centroid}} + Ad^2$$

Ex rect beam has width 1000m height $h=200$. Calc moment inerte about base of rect.

Deflection of Cantilevered Beam



P : applied force

L : beam length

E : Youngs Modulus

I : Second Moment of Area

δ : deflection

$$\delta_{\text{max}} = \frac{PL^3}{3EI}$$

$$\text{Stiffness} = \frac{3EI}{L^3}$$

Point load @ free end

$$\delta_{\text{max}} = \frac{wL^4}{8EI}$$

$$K = \frac{8EI}{L^4}$$

Uniformly dist load


$$\delta_{\text{max}} = \frac{ML^2}{2EI}$$

applied moment @ free end


You can reduce δ by: $\downarrow P \downarrow L \uparrow E \uparrow I$

Shear Force and Bending Moment Diagrams

Single Load





Distributed Load




Cyclical Loading : Fatigue

- Fatigue is the progressive and localized structural damage that occurs when material is subject to repeated loading and unloading cycles.
- We can use stress life curves to predict # of cycles (N) a steel member can endure at given cyclical stress (S)




Heat Transfer



Modes of Heat Transfer

Conduction

1D heat transfer through material



k : thermal conductivity

$$q_k = \frac{kA}{L} (T_1 - T_2)$$

Fourier's Law


Thermal Resistance

$$q_k = \frac{T_1 - T_2}{R_k}$$

$$R_k = \frac{L}{kA}$$

Convection

heat transfer from surface to moving fluid



\bar{h}_c : avg convective heat transfer

Newton's cooling law


$$q_c = \bar{h}_c A (T_s - T_{\infty})$$

$$q_c = \frac{T_s - T_{\infty}}{R_c}$$

$$R_c = \frac{1}{\bar{h}_c A}$$

Radiation

heat transfer through electromagnetic waves from one surface to another





$$q_r = A, F_{1-2} \sigma (T_1^4 - T_2^4) = \frac{T_1 - T_2}{R_r}$$

$$R_r = \frac{T_1 - T_2}{A, F_{1-2} \sigma (T_1^4 - T_2^4)}$$

q = heat transfer rate (W)

Conduction : heat transfer from more energetic to less energetic particles

heat transfer across this medium in contact



Fourier's Law:

$$q''_k = -K \frac{dT}{dx}$$

heat flux (W/m²)

temp. gradient

thermal conductivity


-ve due to ht in direction of ↓ temp.

But... under SS conditions, temp. is linear so $\rightarrow q''_k = -K \frac{T_2 - T_1}{L}$

1.2.2 - Convection

Comprised of:

① Random molecular motion (diffusion) ② Bulk, macroscopic motion of fluid



if $T_s > T_\infty$:

ht via convection
Occurs from
Surface to fluid

$$q'' = h (T_s - T_\infty)$$

temp.


heat flux (W/m²)

convection heat transfer (W/m²K)

Surface ($u=0$): random motion only

Forced vs. Natural Convection

a → forced convection
b → natural convection
c → boiling
d → condensation




3 laws thermodynamics

① conservation of energy • used to find energy, heat loss efficiency
② disorder increases. As disorder ↑ energy transformed into less usable forms. Efficiency will be always < 100%
③ molecular movement stops @ absolute zero - 273°C. At this temp perfect crystal no disorder.

1.2.3 - Radiation

- ↳ energy emitted by matter at non-zero temp.
- ↳ energy transported by EM Waves
- ↳ doesn't require a material medium



①: radiation emitted from surface

$$E = \varepsilon \sigma T_s^4$$

emissive power

emissivity

Stefan-Boltzmann constant

($0 \leq \varepsilon \leq 1$)

($\sigma = 5.67 \times 10^{-8} \text{ W/m}^2\text{K}^4$)

if $\varepsilon = 1 \rightarrow$ blackbody

②: radiation incident on a surface from surroundings


$$G_{\text{abs}} = \alpha G$$

irradiation

absorbed by surface

absorptivity

($0 \leq \alpha \leq 1$)



$$T_{\text{sur}} \neq T_s$$

open Surroundings


enclosed Surface

Radiation Eqn: $q''_{\text{rad}} = \frac{q}{A} = \varepsilon E_b(T_s) - \alpha G = \varepsilon \sigma (T_s^4 - T_{\text{sur}}^4)$

net radiation heat transfer from surface

$$q''_{\text{rad}} = \varepsilon \sigma (T_s^4 - T_{\text{sur}}^4)$$


GD&T




GD&T: System to define and communicate tolerances on engineering drawings. It provides info on shape, size, positional relationship and allowable error for form and position.

Difference between coordinate/size and geometric tolerance:

Size



geometric



Modifier GD&T Symbols

TERM	4.5
	2018
Maximum Material Condition	(M)
Maximum Material Boundary	(M)
Least Material Condition	(L)
Least Material Boundary	(L)
Translation	(D)
Projected Tolerance Zone	(P)
Free State	(F)
Tangent Plane	(T)
Unequally Disposed Profile	(U)
Independency	(I)
Statistical Tolerance	(ST)

Geometric Characteristic Symbols

SYMBOL	GEOMETRIC CHARACTERISTIC	TOLERANCE TYPE	CONTROL SUMMARY
	FLATNESS		
	STRAIGHTNESS		
	CYLINDRICITY		
	CIRCULARITY (ROUNDNESS)		
	PERPENDICULARITY	ORIENTATION (NO RELATION BETWEEN FEATURES)	CONTROLS FORM (SHAPE) OF SURFACES AND CAN ALSO CONTROL FORM OF AN AXIS OR MEDIAN PLANE DATUM REFERENCE IS NOT ALLOWED
	PARALLELISM		
	ANGULARITY		
	POSITION		
	PROFILE OF A SURFACE	LOCATION	LOCATES CENTER POINTS, AXES, AND MEDIAN PLANES FOR SIZE FEATURES ALSO CONTROLS ORIENTATION
	PROFILE OF A LINE		LOCATES SURFACES ALSO CONTROLS SIZE, FORM, AND ORIENTATION OF SURFACES BASED ON DATUM REFERENCE
	TOTAL RUNOUT	RUNOUT	CONTROLS SURFACE COAXIALITY ALSO CONTROLS FORM AND ORIENTATION OF SURFACES
	CIRCULAR RUNOUT		
	CONCENTRICITY	LOCATION (DERIVED MEDIAN POINTS)	LOCATES DERIVED MEDIAN POINTS OF A FEATURE NOT COMMON... CONSIDER USING POSITION, RUNOUT, OR PROFILE
	SYMMETRY		


Individual features application

↳ doesn't depend on neighboring features


Related Features application

I/R

Types of Parts




Axis symmetry parts



Prismatic parts

- planar surfaces



3-D Contour Parts

- linear + circular surfaces

Based on type of part,
we must choose
symbols to fabricate it



Form Control (4 Symbols)


① Straightness

2 types: surface straightness and axis straightness



Surface



feature control frame




Axis




Example

Straightness without GD&T:



very expensive for
such a simple part

Straightness with GD&T



Use Case: designing pipes that must
be straight

Maximum Material Condition





• Use mm when part function depends on fit and assy clearance

② when part function depends on strength material, or minimum wall thickness

Flatness

: only applied to prismatic parts where you have planar surface





3 Step Verification

- ① Size within drawing limits
- ② Part has to be in boundary of max material condition
- ③ Peak & valley difference



Circularity

: only applied to axis symmetry parts w/ circular x-section



Cylindricity

: Straightness and circularity both for axis symmetry part



Orientation Control (3 symbols)

Datum


: Used to create a relationship between surface we want to control and existing surface



Datum Feature: Feature on the object that is restrained

Datum: theoretical perfect surface corresponding to the feature

Datum Simulator: real imperfect surface used to immobilize part to approx perfect






- Part in space has 6 degrees freedom
- If you hold datum feature against datum sim 3 DOF are constrained
- Hold against two sims then 5 DOF X
- Hold against 3 sims then part immobile





- Datums establish datum reference frame (coord syst to inspect feature)
- Order of which datums applied matters bc all real surfaces are imperfect.




① **Parallelism** : controls how close feature is to being parallel with a datum



② **Angularity** :




Perpendicularity : same as parallelism but 90°



Location Control (3 symbols) (position best)

Position: defines maximum distance a plane or axis can be away from theoretically exact position. Used to define location of holes.



True Position: theoretically exact position of the feature called out by **basic** dimensioning.

3 Problems w/ coordinate dimensioning

1. Rectangular tolerance zone 57% larger
2. tolerance can't change using **M** based on feature size
3. doesn't give you reference to measure from




Another advantage of GD&T is that allows you to explicitly define relevant datums and what order they should be considered.







• Primary datum is usually chosen as the one perpendicular to axis of hole.

Profile of a Surface

: follows the shape of the feature with width of specified tolerance




Profile of a Line



Runout

Runout : Used to describe the eccentricity of a surface relative to a particular axis

Circular Runout : Controls the roundness of individual cross sections of a feature relative to a datum axis




Similar to circularity, except O runout uses datum so tolerance zones must be centered on the datum axis.

Circularity vs Runout?

- slice cucumber 1/2 check if round
- ↗ shear cucumber and check if it wobble
- guarantee feature is round
 - ↗ + aligned to datum axis

Total Runout

Used to control runout in axial direction as well so tolerance zone is defined by two concentric cylinders



Circular Runout: hold marker on outside of tire and rotate. Low wobble means runout good. Lot of wobble is bad

Total Runout: Move marker along width of tire as you rotate line should be smooth for low runout

DFM
&
DFA




Design for Manufacturing

Injection Molding

Process

1. Plastic Pellets are fed into the injection unit through a hopper
2. Screw rotates to transfer pellets forward, melting them in the process
3. Once at the front, pellets are entirely molten
4. Screw plunges forward, injecting molten plastic into the cavity image
5. Plastic solidifies → Mold Opens → Part is Ejected
6. Mold Closes → Repeat



From left to right, the components are: ram (1), screw (2), hopper (3), barrel (4), heaters (5), materials (6), nozzle (7), mold (8), and part (9).

Design Techniques:

1. Use constant wall thickness (1 – 3 mm) → prevents warping and sinking
2. Hollow out thick sections, then add ribs to increase stiffness
3. Add smooth transitions (i.e. fillets, chamfers) for parts with multiple wall thicknesses
4. Round all edges to avoid stress concentrations
5. Add draft angles (min 2 degrees)
6. Move part line to intersect with undercut
7. Add ribs to increase stiffness, rather than increasing thickness

Tolerance of 0.1 (general) to $\pm 0.02s$

Materials:

Plastics including:

a. ABS

- Variety of modifications can be made to ABS to enhance impact resistance, toughness and heat resistance
- Molding at high temp. improves impact resistance, toughness & heat resistance
- Molding at low temp. improves strength and impact resistance
- Examples: pipes, automotive parts, kitchen appliances, Lego bricks, etc.

b. Polyethylene

- high levels of ductility, tensile strength, impact resistance, resistance to moisture absorption, and recyclability
- Examples: Plastic bags, bottles, etc.

c. Polycarbonate

- Can undergo large plastic deformations without cracking or breaking
- Main properties: impact resistant and transparency
- Examples: greenhouses, DVD, eyewear lenses, automotive components and phones

d. Nylon (Polyamide)

- Tough, wear/abrasion resistant and chemical resistant
- Apparel, footwear, sports equipment, automotive products, etc.

e. High Impact Polystyrene

- brittle

f. Polypropylene

- Flexible, high melting point, high resistance to stress, great impact strength and doesn't break down when reacting with chemicals (ex. Utensils, batteries, etc.)

Casting

Process:

- Minimum thickness: 5mm
- Low-cost process that can produce parts in large quantities with no limit in size, shape or complexity, here's the process:
 1. A pattern made out of metal/wood is used to form the cavity, where the molten metal is poured
 2. Holes are created by sand cores into the mold
 3. Pour molten metal into mold, then cool down

Design Techniques:

1. All sections designed with a uniform thickness
2. Design should include gradual change from section to section, where necessary
3. Adjoining sections should be designed with generous fillets
4. A complicated part should be designed as two or more simple castings to be assembled by fasteners or by welding

Materials:

- a. Steel
 - Most difficult to produce due to steel's high melting temperature
 - This can aggravate casting problems
- b. Gray Iron
- c. Brass
- d. Bronze
- e. Aluminum

Process	Advantages	Disadvantages	Examples
Sand	Wide range of metals, sizes, shapes, low cost	poor finish, wide tolerance	engine blocks, cylinder heads
Shell mold	better accuracy, finish, higher production rate	limited part size	connecting rods, gear housings
Expendable pattern	Wide range of metals, sizes, shapes	patterns have low strength	cylinder heads, brake components
Plaster mold	complex shapes, good surface finish	non-ferrous metals, low production rate	prototypes of mechanical parts
Ceramic mold	complex shapes, high accuracy, good finish	small sizes	impellers, injection mold tooling
Investment	complex shapes, excellent finish	small parts, expensive	jewellery
Permanent mold	good finish, low porosity, high production rate	Costly mold, simpler shapes only	gears, gear housings
Die	Excellent dimensional accuracy, high production rate	costly dies, small parts, non-ferrous metals	precision gears, camera bodies, car wheels
Centrifugal	Large cylindrical parts, good quality	Expensive, limited shapes	Pipes, boilers, flywheels

Sheet Metal Forming Design Techniques

Holes

1. Distance between holes and edge $> 1.5x - 2x$ thickness
2. Bending radius at least $1.5T$
3. Hole diameter should be at least equal to part thickness
4. Distance between holes should at least be $2T$ or greater

General

5. Uniform wall thickness
6. Consistent bend radius (saves time and money)
7. Bend sheet metal in the same plane (to avoid need for reorientation, saving time and money)
8. To prevent parts from fracturing or distorting, make sure to keep the inside bend radius at least equal to the sheet's thickness
9. Outside radius of curls must be at least twice the sheet's thickness
10. Max. depth of a countersink is $3.5x$ material thickness
11. Add collars to increase stiffness around piercings

Bends

12. Add bend relief to strengthen sheet metal parts
13. Bends at edges reduce likelihood of metal tearing

Spring-Back Effect

14. Add chamfers to corners and beads to bends to reduce spring-back effect

spring-back occurs when metals try to go back to original shape after being bent

Designing for Machining Rules of Thumb

- Design parts that can be machined with the tool of the largest possible diameter.
- Add the large fillets (at least $\frac{1}{3} x$ cavity depth) to all internal vertical corners.
- Limit the depth of cavities to 4 times their width.
- Align design main features along one of six principal directions
- Avoid really thin parts ($\sim 0.5\text{mm}$ or 0.02in) to avoid warping or bending of part after machining

DFM Summary

- We want minimal part counts that are easy to produce and assemble
 - To achieve this, answer the following questions:
 1. Do parts move relative to each other?
 2. Do parts need insulation?
 3. Do parts need to be made out of different materials?
 4. Will combining parts complicated maintenance?
 5. Will combining parts interfere with assembly of other parts?
 - If answer is No to all questions, then combine parts
 - Reducing part count, reduces assembly time, reducing cost
- Avoid sharp corners, deep holes and thin walls, so parts don't get distorted

Injection Molding vs Die Casting

Benefits of Injection Molding:

- Production is quicker due to more flexibility in the molding process
- Plastic Injection molds can accommodate different plastic or polymer materials
- Fillers can be used in plastic molds to increase strength
- Efficient process with very accurate finishes

Benefits of Die Casting:

- Efficient process with a high degree of accuracy
- No need for secondary operations
- Complicated designs can be more easily cast
- Produces higher-quality products with better tolerance that will last longer

Drawbacks of Die Casting:

- Not applicable for metals with high melting points
- Large lead times
- Can't cast large parts

IM: If you are looking to produce lots of inexpensive parts since labor and material costs are relatively low.

DC: If accuracy in design is a priority or you need many complex parts in a short time frame. More durable and higher quality feel when you go with metals over plastics.

Benefits of Injection Molding over Die Casting, Machining and Sheet Metal Forming:

1. Cost Savings
2. Lighter weight
3. Can form complex shapes, relative to sheet metal forming
4. Noise reduction if parts consistently come in contact
5. Skip the paint when using plastics
6. Plastic less prone to scratches and dents
7. Plastics don't corrode

Design for Assembly (DFA)

Guidelines

1. Reduce number of parts
2. Use common and standardized parts
3. Design for ease of fabrication by:
 - a. Use near net shapes to minimize the required machining and processing
 - b. Avoid designs with sharp corners (induce stress concentrations)
 - c. Avoid undercuts as they require additional costly tools
 - d. Design work pieces to used standardized cutters and drill bit sizes
4. Mistake proof the assembly process
 - a. Notches, asymmetrical holes and stops can be used to ensure the assembly process is unambiguous
5. Use efficient joining and fasteners
 - a. Use self-threading screws or adhesives (nuts and bolts are time consuming)
6. Self-fastening components
7. Self-locating components

Mechanical Engineering Basic Questions

Stiffness vs Strength?

Strength is a ability of a material to withstand an applied load without getting plastically deformed or breaking.

Stiffness is the degree to which an object resists its deformation in applied load.

Hardness vs Toughness?

Hardness: A material's ability to withstand friction or resist abrasion.


Toughness: How well the material can resist fracturing when force is applied (or how much energy it can absorb before breaking → more energy = tougher)

- **Ex:** Crumple zones on cars
- **Ex:** silly putty is technically tough

Steel vs Aluminum?

- Aluminum is more malleable and flexible than steel
- Aluminum can be pushed to dimensional limits without breaking, unlike steel
- Steel is tougher and more resilient
- Aluminum is corrosion resistant
- Steel is harder than aluminum
- Steel is less likely to deform or bend under weight
- Steel is 2.5x denser than aluminum
- Aluminum is 1/3 the weight of steel
- Aluminum is cheaper than stainless steel
- Aluminum is difficult to weld
- Steel is stronger (assuming weight isn't an issue)

Formulas



Force Equation

$$F = ma$$

F = force
m = mass
a = acceleration

Torque Equations

$$\tau = FL$$

$$\tau = I\alpha$$

τ = torque
F = force
L = distance to pivot point
I = moment of inertia about pivot
 α = angular acceleration

Energy Equations

$$E_{kinetic} = \frac{1}{2}mv^2$$

$$E_{rotational} = \frac{1}{2}I\omega^2$$

$$E_{gravitational\ potential} = mgh$$

$$E_{spring\ potential} = \frac{1}{2}kx^2$$

E = energy
m = mass
v = velocity
I = moment of inertia
 ω = angular velocity
g = gravitational acceleration
h = height
k = spring constant
x = spring displacement

Stress Equations

$$\sigma = \frac{F}{A}$$

$$\sigma_{hoop} = \frac{Pr}{t}$$

$$\sigma_{axial} = \frac{Pr}{2t}$$

$$\sigma_{beam\ bending} = -\frac{My}{I}$$

$$\tau = \frac{Tr}{J}$$

σ = stress
P = pressure
r = radius
t = thickness of pressure vessel
M = internal moment
y = distance from neutral axis
I = moment of inertia
 τ = shear stress from torsion
T = torsional torque
J = polar moment of inertia

Moment of Inertia Equations

$$I_{rectangle} = \frac{1}{12}bh^3$$

$$I_{hoop} = mr^2$$

$$I_{solid\ cylinder} = \frac{1}{2}mr^2$$

$$I_{total} = I_c + mh^2$$

I = moment of inertia
b = side parallel to bending axis
h = side perpendicular to bending axis
m = mass
r = radius
 I_c = moment of inertia about center
h = distance from axis of rotation

Kinematics equations

$$v = v_0 + at$$

$$x = x_0 + v_0t + \frac{1}{2}at^2$$

$$v^2 = v_0^2 + 2a(\Delta x)$$

$$a_{centripetal} = \frac{v^2}{r}$$

$$\omega = \frac{v}{r}$$

x = position
v = linear velocity
a = acceleration
t = time
r = radius
 ω = angular velocity

Pressure Equations

$$P = \frac{F}{A}$$

$$P_{hydrostatic} = \rho gh$$

Bernoulli's Equation

$$P_1 + \frac{1}{2}\rho v_1^2 + \rho gh_1 =$$

$$P_2 + \frac{1}{2}\rho v_2^2 + \rho gh_2$$

P = pressure

ρ = density

g = gravity

h = height of fluid

v = velocity

P = pressure

ρ = density

g = gravity

h = height of fluid

v = velocity

w_n = natural frequency

k = stiffness

m = mass

F_{cr} = critical buckling load

E = Young's Modulus

I = moment of inertia

L_e = effective length (differs based on how end points of beam are attached)

Natural Frequency Equation

$$w_n = \sqrt{\frac{k}{m}}$$

Buckling Equation

$$F_{cr} = \frac{\pi^2 EI}{L_e^2}$$

δ_{max} = max deflection of

beam in bending

F = force applied

L = length of beam

E = Young's Modulus

I = moment of inertia

Momentum Equations

$$\rho = mv$$

$$L = mvr$$

Heat Conduction Equation

$$\frac{Q}{t} = \frac{kA(\Delta T)}{\Delta x}$$

ρ = linear momentum

L = angular momentum

Q = heat (Joules)

t = time

k = coefficient of thermal conductivity


A = surface contact area

T = temperature in Kelvin

x = length / distance between the two points

Bolted dry
textbook

bolted joint
not as stiff as number
as far as new tools
grip on 14 N/mm
OK



Max applied load
36 kN ✓ So good
Proof strength ✓
9 N/mm
torque test
on crimp

Alum → die cast

high pressure die
castings
mix of iron/sand casting

Gasket design
b-1 casting